WO 2005/088778 PCT/JP2005/004727

## **Brief Statement**

The written opinion with regard to 2.1, "Unlocking means are in the second connector housing, not in temporary locking means (line 10)" is correct. We amended claim 1 to conform with a specification of page 9, line 12, or FIG. 1.

The wording of "the temporary locking means has a position regulator means" in claim 1 is incorrect. We amended claim 1 to conform with a specification of page 11, lines 24-25, or FIG. 1.

5